






Inline injection pump	Siste
- Camshaft - It have the same rotation as the engine camshaft (one turn for two turns of the crankshaft) -Causes an linear movement on the plungers	temas Automóveis
-Plungers - Push the fuel in the direction of the injector	nóveis
- Gear rack -Causes an rotation movement on the plungers that is function of the accelerator pedal	
- Pump elements - Control the amount of fuel that goes to the injector	
Ano lectivo 2009/2010	



































































































































COMMON RAIL	Siste
- Components - Tank - Pipes - Water separator filter - Manual pump (to bleed off air), - Water sensor - water may cause cavitation, a frequent cause of structural damage - Bleed off screw	stemas Automóveis
Ano lectivo 2009/2010	

